

### Who We Are







### **Our Services**











# **35 YEARS OF EXPERIENCE**





75,000+ BUILDINGS

3 BILLION+
GROSS SQUARE FEET









### **SCOPE OF WORK**

### **FCA** and Primary Equipment Inventory

- County-wide Non-Utility Assets
- 38 buildings, 584K GSF
- User-friendly database to store and manage FCA data (AMS)
- Primary equipment inventory data via Excel





38 Assets

**584K GSF** 



10-Year Needs/SF

\$63.80

Total 10-Year
Renewal Needs
\$37M





Facility
Condition
Needs Index
0.13



Current
Replacement
Value
\$293M



### What Is an FCA?





A visual, nondestructive inspection



Identification of current and projected needs




Includes code upgrades and facility use change needs



Needs are prioritized and have estimated costs

### **FCA Process**






# **Primary Goal of an FCA**

Generate data that can be used to support your facility renewal decisions.



# **Building Systems Inspected**





### What are Renewal Needs?





- Bringing facilities up to current standards, expectations, and function
- Enhancing user/employee safety and mitigating liability
- Renewing lifecycle of existing assets in kind if viable




- Preventive maintenance activities
- Strictly cosmetic changes
- Facility additions or demolition

# **Identifying Renewal Needs**









Enhancing user safety and mitigating liability



Replenishing lifecycle of existing equipment



Maximizing life of newly installed equipment

### What Kind of Need?





- Renewable components
- Cyclical replacement
- Deferred or projected renewal
- Used to forecast future needs



- One-time repairs or replacements
- Accessibility or fire/life safety improvements

## **Pricing Renewal Needs**


- Cost library developed inhouse
- Pre-design basis and granularity
- Uses RSMeans, but not limited strictly to published cost data indices
- Assessors trained to adjust useful life to reflect actual conditions
- Better quality data results in ability to provide realistic budget costs






## **Summary of Findings**







Totals may not add up due to decimal rounding

### The Next 10 Years






Totals may not add up due to decimal rounding


### Construction Dates (based on GSF)






## Construction Dates (based on # of Assets)






## **Space Use** (based on GSF)





# Renewal Needs by System






## Renewal Needs by System



Comparison Analysis




# **Renewal Needs by Classification**



| Deferred Renewal<br>(Recurring)     | Repairs or replacement/rebuilding of major building components that have already exceeded their economically useful service life                      |
|-------------------------------------|---|
| Projected Renewal (Recurring)       | Repairs or replacement/rebuilding of major building components that are, or will be, at the end of their useful service life within the next 10 years |
| Plant Adaption<br>(Nonrecurring)    | Expenditures required to adapt the facility to evolving needs of the county, or to changing standards and codes                                       |
| Corrective Action<br>(Nonrecurring) | Expenditures for repairs needed to correct random and unpredictable deficiencies  |

# **Renewal Needs by Classification**





### **Nonrecurring Priorities**



#### High



- correct safety hazard
- stop accelerated deterioration
- return facility to normal operation

#### Medium



- repairs to prevent further deterioration
- improvements to approach/ entry and access to goods/ services (DOJ ADA, priorities 1 and 2)
- correction of potential safety hazards

#### Low



- improving access to restrooms, etc. (DOJ ADA, priorities 3 and 4)
- compliance with current codes as grandfather clauses expire
- recommended actions not required by code

# **Renewal Needs by Priority**




High Nonrecurring/
Deferred Recurring





# **Renewal Needs by Priority**






Totals may not add up due to decimal rounding

# **Establishing CRVs**





### **FCI and FCNI Calculations**



FCI = 0.02

**Deferred Renewal** 

**CRV** 

FCNI = 0.13


**10-Year Renewal Needs\*** 

**CRV** 


\*Deferred & Projected Renewal + Nonrecurring Needs

### **Condition Metrics**





# **FCNI Ranges** (based on GSF)



# **Buildings with Highest FCNIs**



| ASSET<br>CODE | ASSET NAME                   | BUILT | GSF   | CURRENT<br>REPL VALUE | 10-YEAR<br>NEEDS | FCNI |
|---------------|------------------------------|-------|-------|-----------------------|------------------|------|
| 2079          | LOS ALAMOS LITTLE<br>THEATRE | 1945  | 10.1K | \$6.1M                | \$1.4M           | 0.22 |
| 2031          | FULLER LODGE                 | 1928  | 21.6K | \$10.3M               | \$2.4M           | 0.23 |
| 2023          | FIRE STATION 2               | 1948  | 7.2K  | \$2.9M                | \$722.8K         | 0.25 |
| 2011          | BETTY EHART SENIOR<br>CENTER | 1997  | 18.6K | \$10M                 | \$2.7M           | 0.27 |
| 2003          | ANIMAL SHELTER               | 2010  | 4K    | \$2.1M                | \$599K           | 0.28 |
| 200101        | AIRPORT TERMINAL             | 1947  | 2.5K  | \$2.1M                | \$1.4M           | 0.64 |

#### 2079 - Los Alamos Little Theater



Noncompliant fountain and Dutch door transaction counter



Obsolete trough urinal



Stained and mismatched ceiling

#### 2031 – Fuller Lodge



Access stair with noncompliant handrail



Nonaccessible restroom



Old, dilapidated restroom

#### 2023 - Fire Station 2



Aging boiler



Old restroom fixtures and finishes



Older distribution panel

#### **2011 – Betty Ehart Senior Center**



Aging boiler and pumps



Noncompliant access walk with trip hazard



Old ballasted roofing with aggregate removed

#### 2003 - Animal Shelter



General view of kennel corridor



Noncompliant drinking fountain



Exterior details of kennel

#### **200101 – Airport Terminal**



Leaking noninsulated window and rusty frame



Noncompliant fountain and aging door hardware



Aging parking lot pavement

# **Findings**

- Overall FCNI of 0.13 is comparably low
- Overall FCI of 0.02 reflects focus on overdue items (and young age of GSF as a whole)
- Site needs are significantly higher than typical client



# **Findings**

- HVAC has Highest \$ Needs (\$9.1M)
  - \$200K for one-time improvement actions
  - \$357K deferred renewal
  - \$8.5M renewable components over 10 years
- Pavement is also a priority



# **Conclusions**



- Results are influenced by new construction (60% of GSF constructed since 2003)
  - As the newer building system age at 30-50 years
- reinvestment strategy must already be planned
- Focus of reinvestment should be the older buildings
- Consideration should be given to razing Airport storage
- Site pavement should become a priority

# **Establishing Funding Strategies**



Nonrecurring (Upgrade Costs)

One-time repairs and improvements typically related to code upgrades, ADA compliance, facility use change, etc.

**Deferred Renewal** (Catch-up Costs)

Repairs or renewals (not accomplished as part of routine maintenance or capital repair) that have accumulated to the point that facility deterioration is evident

Projected Renewal (Keep-up Costs)

Planned cyclical renewal efforts due within the next 10 years

### **Set Goals and Targets**



Recommended strategy over the next 10 years

- Reduce catch-up costs (60%)
   (Deferred Renewal)
   \$276K annually
- 2. Fully fund keep-up costs (Projected Renewal)\$2.6M annually
- 3. Address 50% of the upgrade costs (Nonrecurring) \$315K annually



Attachment B

42

## **Set Goals and Targets**



Reinvest \$3.2 million annually

(appx 1.1% of current CRV)



### **Results of Prudent Funding**



Mitigate downtime

Provide more optimal venues for activity and programs



Allows County to provide the highest level of service

Attracts tourism

Consume and pay for less energy

Applies more effective maintenance services



# **OPTIMIZING YOUR INVESTMENT**

in Facilities Management

